


F A D/R E C(A1) A2 A3 T WB F A D/R E C(A1) A2 A3 T WB

FIG. 2



4 t t V

3/3

LSU 640 LOAD BUF 720 720RAW 720RAW 720A 4 addrb RAW rd stage trap_taken 3

-720T

0

2 1 0

FIG. 4




FIG. 5